


CORDUROY CROSSING



IMPROPER INSTALLATION

- Area is too wet for proper application of corduroy
 - Insufficient corduroy to support equipment
 - Corduroy is sunken into wetland soil
- Approaches are steep, rutted, and are not protected with additional corduroy or mats



PROPER INSTALLATION

- No flowing or standing water or saturated soil present
- Adequate amount of layered corduroy to protect soil from rutting
- Approaches are protected from rutting by extension of corduroy beyond edges of crossing